

Calibrating Alpha/Beta Counters with Cs-137

"Instrument problems" reported to Protean following a failed cross-check or QA/QC analysis are sometimes caused by incorrect use of calibration standards. Different errors are reported, the most serious being under-reporting of sample activity. Common mistakes in the selection and use of calibration sources will be discussed, and examples of incorrect calibration source usage will be presented.